



















- [19] Standard ISO 9869-1, Thermal Insulation – Building Elements – In Situ Measurement of Thermal Resistance and Thermal Transmittance, 2014.
- [20] Cardinale N, Guida A, Ruggero F. (2001). Thermohygrometric evaluation in the recovery of rocks buildings of the “Sassi of Matera” (Italy). *Journal of Building Physics* 24(4): 301-315. <http://doi.org/10.1106/ld9b-dnln-r5hj-k01t>
- [21] UNI EN ISO 7730, Ergonomics of the thermal environment - Analytical Determination and Interpretation of Thermal Comfort Using Calculation of The PMV and PPD Indices and Local Thermal Comfort Criteria, 2006.

## NOMENCLATURE

$D_{a,m}$	average of absolute deviations, dimensionless
$n$	Number of year considered, year
$D_{r,m}$	Average of relative deviation, dimensionless
$T_{m1,n}$	averages temperature of winter season calculated for 2002 – 2016 period of ALSIA-Matera data series, °C
$T_{m2,n}$	averages temperature of winter season calculated for 2002 – 2016 period of ilmeteo.it- Gioia del Colle data series, °C